

700 West Mineral Ave  
Littleton, CO 80120



## Network Disclosure Announcement No. 770

Short Term Public Notice Under Rule 51.333(a)

CenturyLink's Internet address: <http://qwest.centurylink.com/disclosures/>

### Copper Retirements in Arizona, Colorado, Minnesota and Washington

**First Implementation Date:** *February 28, 2012*

Original Date Posted:

December 17, 2012

**Summary:**

Copper Retirements are necessary to respond to various factors in the Outside Plant, including road construction, maintenance problems, and growth accommodation. Replacement cables may be either copper or fiber. Specific information will be provided with each disclosure.

**Locations, Timing of  
Deployments & Interface  
Requirements:**

The following gives additional details on the copper retirement(s):

STATE	WIRE CENTER	PLANNED COMPLETION OR RETIREMENT DATE	DA (s)	Job #	FDI Address(es)	Replacing
AZ	Yuma Southeast YUMAAZSE	04-01-2013	410211	E.396500	3183 S Fortuna Ave	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.

STATE	WIRE CENTER	PLANNED COMPLETION OR RETIREMENT DATE	DA (s)	Job #	FDI Address(es)	Replacing
AZ	Yuma Southeast YUMAAZSE	02-28-2013	410212	E.309816	3210 A Arizona Ave	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
CO	Arvada ARVDCOMA	02-28-2013	411231	E.390271	5290 Miller St	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
CO	Denver South DNVRCOSO	06-30-2013	312933	E. 381844	2105 S Galapago	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.

STATE	WIRE CENTER	PLANNED COMPLETION OR RETIREMENT DATE	DA (s)	Job #	FDI Address(es)	Replacing
MN	Maple Grove MPGVMNXA	08-02-2013	24	E. 238444	15053 Weaver Lake Rd	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
MN	Maple Grove MPGVMNXA	06-01-2013	125	E. 238444	West Fish Lake Rd	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
WA	Kingston KGTNWAXX	02-28-2013	OHIOAFC	E.360204	N/A	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.

**Additional Information:**

Any customer premises equipment vendor/manufacturer or enhanced services provider desiring additional technical information in conjunction with this Disclosure can contact:

Abdennaceur Boudhaouia  
Regulatory Compliance Manager  
303-707-8561

[Jamal.Boudhaouia@CenturyLink.com](mailto:Jamal.Boudhaouia@CenturyLink.com)