

700 West Mineral Ave
Littleton, CO 80120



Network Disclosure Announcement No. 780

Short Term Public Notice Under Rule 51.333(a)

CenturyLink's Internet address: <http://www.centurylink.com/disclosures/>
Copper Retirements in Arizona, Iowa, Minnesota, and North Dakota.

First Implementation Date: *February 15, 2015*
Original Date Posted: **December 17, 2014**

Summary: Copper Retirements are necessary to respond to various factors in the Outside Plant, including road construction, maintenance problems, and growth accommodation. Replacement cables may be either copper or fiber. Specific information will be provided with each disclosure.

**Locations, Timing of
Deployments & Interface
Requirements:**

The following gives additional details on the copper retirement(s):

STATE	WIRE CENTER	PLANNED COMPLETION OR RETIREMENT DATE	DA (s)	Job #	Replacing
AZ	Tucson South TCSNAZSO	04-30-2015	928884	E.692762	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.

STATE	WIRE CENTER	PLANNED COMPLETION OR RETIREMENT DATE	DA (s)	Job #	Replacing
AZ	Tucson Cortaro TCSNAZCO	02-15-2015	211615; 211614; 211513; 210511; 210513; 210516	E.699042	Road move in the area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
AZ	Tucson Cortaro TCSNAZCO	03-16-2015	210417; 210412	E.712929	Road move in the area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
AZ	Tucson Cortaro TCSNAZCO	04-16-2015	212612 210411; 210417	E.712991 E.713019	Road move in the area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.

STATE	WIRE CENTER	PLANNED COMPLETION OR RETIREMENT DATE	DA (s)	Job #	Replacing
IA	Indianola INDNIACO	03-16-2015	439001	E.677081	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
MN	Rochester ROCMNRO	05-22-2015	161202; 161203	E.710827	Growth in distribution area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.
ND	Fargo FARGNDBC	02-20-2015	270103, 240203, 270904; 270905, 230702, 271003, 270304, 270203, 250202, 250103, 271004, 230906, 240202, 270405, 230905, 230604, 240203, 230802, 231002, 240103, 270303, 231102, 250104, 250402, 270406, 270202, 230402, 230904, 270302, 271002, 250302, 260105, 231002, 230303	E. 648741	Road move in the area requires CenturyLink to cut facilities to fiber fed digital loop carrier system (DLC). After the cut to DLC, copper reliant services, such as non-loaded copper loops will not be supported. All other types of unbundled loops will still be available.

Additional Information:

Any customer premises equipment vendor/manufacturer or enhanced services provider desiring additional technical information in conjunction with this Disclosure can contact:

Abdennaceur Boudhaouia
Regulatory Compliance Manager
303-707-8561 Jamal.Boudhaouia@CenturyLink.com

